

IPS VideoManager

Release Notes Version 15.11

Updates and changes from version 15.10

Inhalt

1	Bug fixes	2
1.1	Dome Tracker	2

1 Bug fixes

In IPS VideoManager V15.11, several bugs have been corrected.

Serious errors are listed below:

1.1 Dome Tracker

- Fixed a bug that prevented the Accept button from being activated when saving the 3D calibration position. As a result, the Transfer button was also not activated, meaning that the 3D calibration data was not transferred to the Dome Tracker and the dome control could not function correctly.

(VM-298)

Copyright © 2025 Securiton GmbH.

IPS and the IPS logo are registered trademarks of Securiton GmbH.

Securiton GmbH has included the information contained in this manual to the best of its knowledge. Content of this documentation exclusively serves information purposes and may be changed without prior notice. Securiton GmbH accepts no responsibility for damage or accidents, which occur because of information, which has been given regarding devices or components not manufactured by itself. Securiton GmbH accepts no responsibility for changes or modifications, which have not been explicitly authorised by Securiton GmbH.