

Release Note

IPS VideoManager Version 16.2

Updates and changes from version 16.1

1 Features

- The permission to create a system report is disabled by default for all user groups and must be enabled in the system settings for the desired user groups. (VM-16)

2 Improvements

- Number plate recognition using Axis cameras has been improved by changing the verification time for comparison with the white and black lists to an interval of one second. (VM-90, VSD-3173)

3 Bug fixes

3.1 Cameras

- Fixed a bug that prevented changing the transport protocol (HTTP/HTTPS) when configuring ONVIF cameras. (VM-102)
- Fixed a bug that prevented entering port numbers (HTTP/HTTPS) when configuring ONVIF cameras. (VM-102)
- Fixed a bug that prevented the opening of the Axis P3268-LV camera in the IPS VideoManager system configuration when it was configured as an ONVIF camera. (VMD-21577)

3.2 System

- Fixed a bug that prevented the management from reading parameters from Settings.xml after they had been changed or created using ServiceManager. As a result, the client could no longer log in to the management.

If the error has already occurred, the damaged Settings.xml file in the **data path** → **VideoManager\Management** must be deleted and the management then restarted. The Settings.xml file will be recreated and can be edited with the repaired ServiceManager. (VM-72, VSD-3153)

Copyright © 2025 Securiton GmbH.

IPS and the IPS logo are registered trademarks of Securiton GmbH.

Securiton GmbH has included the information contained in this manual to the best of its knowledge. Content of this documentation exclusively serves information purposes and may be changed without prior notice. Securiton GmbH accepts no responsibility for damage or accidents, which occur because of information, which has been given regarding devices or components not manufactured by itself. Securiton GmbH accepts no responsibility for changes or modifications, which have not been explicitly authorised by Securiton GmbH.