IPS VideoManager

Release Notes Version 16.9

Table of Contents

1 Bug fixes 1

1.1 IPS MultiSite Client 1

1.2 IPS Management Service & IPS CentralManagement Service 1

1.3 IPS DiagnosticService 1

2 Note: PHP security vulnerabilities 1

1 Bug fixes

In IPS VideoManager V16.9, several bugs have been corrected. Serious errors are listed below:

1.1 IPS MultiSite Client

- Fixed an issue which prevented the correct display of an Alarm Single Image after a first alarm was acknowledged or the user switched from a different alarm. The message **No H.26x WAN streaming profile available!** was shown instead.

  This issue occurred when only a MJPEG recording profile was set and IPS MultiSite Streaming Service was configured.

  VM-1021, VSD-3226

1.2 IPS Management Service & IPS CentralManagement Service

- Fixed an issue which prevented the correct incorporation of the SQL instance SQLEXPRESS into the data source of the connection string.

  VM-1069

1.3 IPS DiagnosticService

- Fixed an issue which caused the IPS DiagnosticService during establishment of a network socket to use the wrong network adapter if more than one adapter was available.

  VM-425, VSD-3166

2 Note: PHP security vulnerabilities

On 21 October 2026, the Federal Office for Information Security (BSI) issued a warning about a threat posed by critical vulnerabilities in the PHP programming language. The IPS VideoManager is not affected by these vulnerabilities.

© IPS
A Business Unit of Securiton GmbH

Copyright © 2026 Securiton GmbH.

IPS and the IPS logo are registered trademarks of Securiton GmbH.

Securiton GmbH has included the information contained in this manual to the best of its knowledge. Content of this documentation exclusively serves information purposes and may be changed without prior notice. Securiton GmbH accepts no responsibility for damage or accidents, which occur because of information, which has been given regarding devices or components not manufactured by itself. Securiton GmbH accepts no responsibility for changes or modifications, which have not been explicitly authorised by Securiton GmbH.