

Release Note

IPS VideoManager Version 15.9

Updates and changes from version 15.8

1 Bug fix

- Fixed a bug that prevented the opening of the Axis P3268-LV camera in the IPS VideoManager system configuration when it was configured as an ONVIF camera. (VMD-21577)

Copyright © 2025 Securiton GmbH.

IPS and the IPS logo are registered trademarks of Securiton GmbH.

Securiton GmbH has included the information contained in this manual to the best of its knowledge. Content of this documentation exclusively serves information purposes and may be changed without prior notice. Securiton GmbH accepts no responsibility for damage or accidents, which occur because of information, which has been given regarding devices or components not manufactured by itself. Securiton GmbH accepts no responsibility for changes or modifications, which have not been explicitly authorised by Securiton GmbH.