

IPS VideoManager

Release Notes Version 16.7

Table of Contents

1	IT Security	2
1.1	Securiton Certificate	2
2	Bug fixes	2
2.1	APNR: Barrier stays open	2
2.2	ONVIF camera: black video window	2

1 IT Security

1.1 Securiton Certificate

- IPS VM Client and IPS MultiSite Client are now digitally signed with the Securiton Certificate. Users can verify that the files have not been compromised (File → Properties → Digital Signatures).

2 Bug fixes

In IPS VideoManager V16.7, several bugs have been corrected. Serious errors are listed below:

2.1 APNR: Barrier stays open

- Fixed an issue which caused a barrier to remain open permanently after the vehicle's number plate had been successfully recognised and the vehicle had passed through.

The issue: Two events were triggered for each vehicle, and the second one wrongly caused another opening of the barrier.

VSD-3225

2.2 ONVIF camera: black video window

- Fixed an issue which could lead to a black window in IPS VM Client and IPS NextGen Client where the video stream of an ONVIF camera should have been displayed.

The issue: After specific settings were carried out and saved in IPS System Configuration the resolution 0*0 was saved in the streaming profiles.

VSD-3238

Copyright © 2026 Securiton GmbH.

IPS and the IPS logo are registered trademarks of Securiton GmbH.

Securiton GmbH has included the information contained in this manual to the best of its knowledge. Content of this documentation exclusively serves information purposes and may be changed without prior notice. Securiton GmbH accepts no responsibility for damage or accidents, which occur because of information, which has been given regarding devices or components not manufactured by itself. Securiton GmbH accepts no responsibility for changes or modifications, which have not been explicitly authorised by Securiton GmbH.