

IPS VideoManager

Release Notes Version 16.8

Table of Contents

1	Bug fixes	2
1.1	IPS VM Client.....	2
1.2	IPS DiagnosticService.....	2
1.3	IPS VideoManager	2

1 Bug fixes

In IPS VideoManager V16.8, several bugs have been corrected. Serious errors are listed below:

1.1 IPS VM Client

- Fixed an issue which lead to a memory leak that caused the IPS VM Client to eventually use the complete RAM of a computer. This bug fix also enables Privacy Protection zones and objects to be blurred in IPS VM Client.

The IPS Video Renderer Filter must not be used. In the **IPS Client settings → 08 Video streaming → Video renderer** the video renderer must be switched to **Standard**.

Note: An exception applies to the Wall Client when used with Nvidia graphics cards. The temporary workaround mentioned in IPS VideoManager Release Notes V17.1 using the IPS Video Renderer Filter must continue to be applied in this case.

VSD-3241

1.2 IPS DiagnosticService

- Fixed an issue which prevented the correct display of umlauts and special characters by switching from ASCII to UTF-8.

Third-party SNMP applications may work with ASCII and therefore be unable to display umlauts and special characters. Workaround: Do not use umlauts and special characters in names for cameras, camera groups and IO devices.

VSD-3205

- Fixed an issue which prevented the import of additional files in the MIB format if they were not explicitly listed in the file Targets.xml.

VSD-3166

1.3 IPS VideoManager

- In IPS VideoManager V16, some of the user interface text was missing in Spanish, French, Italian and Russian languages.

Copyright © 2026 Securiton GmbH.

IPS and the IPS logo are registered trademarks of Securiton GmbH.

Securiton GmbH has included the information contained in this manual to the best of its knowledge. Content of this documentation exclusively serves information purposes and may be changed without prior notice. Securiton GmbH accepts no responsibility for damage or accidents, which occur because of information, which has been given regarding devices or components not manufactured by itself. Securiton GmbH accepts no responsibility for changes or modifications, which have not been explicitly authorised by Securiton GmbH.